

August 26, 2020

To whom it may concern:

On August 26th erosion/sediment control and Floodplain Violation inspections were performed at 429/431 Kriesel Drive Lot 26.

Significant un-permitted work was performed within the floodplain. Floodplain violations will follow this letter.

Immediately, erosion control shall be re-established along the creek bank.

If repairs are not completed by 5 pm, the City will instruct its on-call erosion control contractor to make the necessary repairs and ***the permit holder will be billed for the repairs.***

A Stop work order has been placed on the project by both the Engineering and Planning and Development Departments pending the floodplain violations.

In the event of a 2nd Violation of Non-Compliance, the City shall:

- Issue a stop work order
- Complete the necessary repairs *at the owner's expense*
- Re-inspect the property. The contractor must call for re-inspection and pay a re-inspection fee of \$55.

In the event of a 3rd Violation of Non-compliance, the City shall:

- Issue a stop work order
- Complete the necessary repairs *at the owner's expense*
- Re-inspect the property. The contractor must call for re-inspection and pay a re-inspection fee of \$55.
- **Issue a citation to appear in court with possible fines and penalties assessed.**

Please call or email for a re-inspection when the repairs are completed.

Thank you for your cooperation.

Lorie Crandell

City of Raymore, Stormwater Quality Specialist

100 Municipal Circle

Raymore, Mo. 64083

(816) 331-1852

